

Work Order ID 147035

147035

Page 1

Friday, May 27, 2016 2:41:48 PM

Item ID: D407-559-115 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Compatible
 Start Date: 5/30/2016 Start Qty: 1.00 ***1*** Cust Item ID:
 Required Date: 6/7/2016 Req'd Qty: 1.00 ***1*** Customer:
 Reference:

Approvals: Process Plan: dm Date: 16/05/27 Tooling: Date: Run Start ***NR1***
 QC: Date: SPC (Y/N): Date: Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
DSI 9624	REV A								
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy blue file and type labels per PPP D407-559-115								
151	Pick Kit	0.00							
151									
Packaging	Memo	0.00							
Packaging									
160	QC4- 100% Inspect kits for completeness	0.00							
160									
QC	Memo	0.00							
Quality Control									

MCS 16-05-30

See attached
MCS

DAS
27
9-89

MAY 31 2016

MAY 30 2016

DAS
6
9-89

DAS
28
9-89

DAS
27
9-89

MAY 31 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐				
Date : _____	Step #: _____	QTY Effective : _____			MRB (QSI042) Approval ☐	
Description Work Order Deviation		Disposition			Completed By _____	
					Lead hand / Supervisor Approval Verification ☐	
					QC / QA Coordinator Approval ☐	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
OTHER : ☐ _____						

Work Order ID 147035***147035***

Page 2

Friday, May 27, 2016 2:41:48 PM

Item ID: D407-559-115

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Compatible

Start Date: 5/30/2016 Start Qty: 1.00 ***1***

Cust Item ID:

Required Date: 6/7/2016 Req'd Qty: 1.00 ***1***

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

170

Identify as per dwg & Stock Location: _____

0.00

170

Packaging

Memo

0.00

Packaging

fg 014

DAS
27
9-89

MAY 31 2016

180

QC21- Final Inspection - Work Order Release

0.00

180

QC

Memo

0.00

Quality Control

MCS

MAY 31 2016

MCS

MAY 31 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause			FAULT CATEGORY							
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date ☐	☐	Manufacturing Process								
Misidentified ☐	☐	Past Due								
			OTHER : _____							

Picklist Print

Friday, May 27, 2016 2:41:54 PM

Page 1

Work Order ID: 147035

147035

Parent Item: D407-559-115

D407-559-115

Parent Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Compatible

Start Date: 5/30/2016

Required Date: 6/7/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP REV:A NEW ISSUE 12-07-23 JLM VERIFIED BY:DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D2274

Manufactured

No

Each

390.0000

12

D2274

Radius Block

DAS
6 28
9-89 9-89

Location

Loc Qty

Loc Code

FG

12

86855

12

ST006

378

144391

378

12

D2529

Manufactured

No

Each

523.0000

12

D2529

Washer

DAS
6 28
9-89 9-89

Location

Loc Qty

Loc Code

ST008

523

143819

273

145269

250

12

D2432-3

Manufactured

No

Each

1.0000

2

D2432-3

206 (24") Bearpaw

139891

DAS
6 28
9-89 9-89

Location

Loc Qty

Loc Code

ST454a

1

139891

1

D4011-1

Manufactured

No

Each

141.0000

6

D4011-1

Clamp, Short

DAS
6 28
9-89 9-89

Location

Loc Qty

Loc Code

ST544

141

145016

141

6

MAY 30 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width:100%; border: none;"> <tr> <td style="border: none;">Skid-tube ☐</td> <td style="border: none;">Cross tube ☐</td> <td style="border: none;">Water Jet ☐</td> <td style="border: none;">Engineering ☐</td> </tr> <tr> <td style="border: none;">Machining ☐</td> <td style="border: none;">Small Fab ☐</td> <td style="border: none;">Prod. Eng. Coord. ☐</td> <td style="border: none;">Quality ☐</td> </tr> <tr> <td style="border: none;">Thermoforming ☐</td> <td style="border: none;">Finishing ☐</td> <td style="border: none;">Rec/Store/Packaging ☐</td> <td style="border: none;">Other ☐</td> </tr> <tr> <td style="border: none;">Large Fab ☐</td> <td style="border: none;">Composite ☐</td> <td style="border: none;">Supplier ☐</td> <td></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																		
Description Work Order Deviation				Disposition				Completed By																	
Root Cause				FAULT CATEGORY																					
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong															
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions															
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance															
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect															
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing															
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved															
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing															
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish															
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread															
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence															
Past Expiry Date ☐	☐	Manufacturing Process	OTHER : _____																						
Misidentified ☐	☐	Past Due																							

Picklist Print

Friday, May 27, 2016 2:41:54 PM

Work Order ID: 147035

147035

Parent Item: D407-559-115

D407-559-115

Parent Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Compatible

Start Date: 5/30/2016

Required Date: 6/7/2016

Start Qty: 1.00

Required Qty: 1.00

D4012-1 Manufactured No

Each 49.0000 6

D4012-1

Cushion

BAS
27
9-89

Location Loc Qty Loc Code

FG 5

133458 5

ST545 44

144666 44

Each 137.0000 12

**

DAS 6 DAS
9-89 28
9-89

AN4-20A Purchased No

AN4-20A

Bolt

BAS
27
9-89

Location Loc Qty Loc Code

GA 24

m116419 24

over003 60

m134039 60

ST343 53

m133694 15

m134634 38

Each 3,939.000 12

**

DAS 6 DAS
9-89 28
9-89

NAS1149D0463J Purchased No

NAS1149D0463J

WASHER

BAS
27
9-89

Location Loc Qty Loc Code

GA 146

M132035 21

M134508 125

ST260a 3600

M134754 2600

M134852 1000

ST263 193

M134634 193

**

DAS 6 DAS
9-89 28
9-89

MAY 30 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : ☐					

Picklist Print

Page 3

Friday, May 27, 2016 2:41:54 PM

Work Order ID: 147035

147035

Parent Item: D407-559-115

D407-559-115

Parent Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Compatible

Start Date: 5/30/2016

Required Date: 6/7/2016

Start Qty: 1.00

Required Qty: 1.00

MS21042L4

Purchased

No

Each

2,786.000

12

MS21042L 4

Locknut

134606

DAS
28
9-89
DAS
6
9-89

MAY 30 2016

DAS
27
9-89

Location

Loc Qty

Loc Code

GA

187

m133769

187

OVER007

2000

m134762

1000

m134861

1000

ST303

502

m134606

3

m134676

499

ST305

97

m130922

97

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS D206-559 Rev. L AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D206-559 REV. 3

REF CANADIAN STC: SH92-17

REF FAA STC: SH1031NE

REF LBA STC: 0796/3034

REF JCAB STC: STC-90-TYO

REF BRAZIL STC: 2010S10-08

1.0 PURPOSE

The purpose of this Dart Service Instruction is to add the D407-559-115 Bearpaw Kit to this approval. The D407-559-115 Bearpaw Kit is designed to be compatible with D206-642-311/-312/-313/-314/-411/-412/-413/-414 Skidtubes equipped with D206-642-XXX Run-On Landing Wearplates. The D407-559-115 Bearpaw Kit is also compatible with the D206-642-XXX Skidtubes equipped with standard wearplates/wearshoes.

2.0 INSTALLATION

To install D407-559-115 Bearpaw Kit on Dart D206-642-XXX Skidtubes equipped with D206-642-XXX Run-On Landing Wearplates refer to Figures 1 & 2 of this Service Instruction as well as the following:

- 2.1 Jack up the aircraft and ensure the skidtubes are serviceable in accordance with ICA-D206-642.
- 2.2 Position D2432-3 Bearpaw on the aft end of each skidtube so that the bearpaw clamps are located on either side of the aft saddle as shown in Figure 1a - 1c of this Service Instruction. The bearpaws should be installed over the run-on landing wearplates.
- 2.3 Attach the D4011-1 Clamps with D4012-1 Cushions using hardware shown in Figure 2 of this Service Instruction. Additional AN960JD416 (or NAS1149D0463J) washers may be installed under the nuts to ensure 1.5-4 threads in safety on the bolts. Although not generally necessary, it is also acceptable to replace the AN4-20A bolts with longer or shorter AN4 bolts, if required.

CAUTION: The torque on the nuts should be limited to 20 in-lb (2.3 Nm)

- 2.4 Lower the aircraft.
- 2.5 Update the aircraft log book to indicate installation of the D407-559-115 Bearpaw Kit and adjust the empty weight and balance record for the rotorcraft with the information given in section 5.0 of this service instruction.

3.0 MAINTENANCE

The D407-559-115 Bearpaw Kit should be maintained in accordance with ICA-D206-559.

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: [Signature]
D. SHEPHERD (DE # 02)

DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7


A	NEW ISSUE	AP	12.07.05
REV.	DESCRIPTION	BY	DATE
DESIGN	AP	DART AEROSPACE LTD	
DRAWN	AP	HAWKESBURY, ONTARIO, CANADA	
CHECKED	99	DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9624	SHEET 1 OF 4
APPROVED	149	TITLE	SCALE
DE APPR.	TH	BEARPAW INSTALLATION	NTS
DATE	12.07.05	COPYRIGHT © 2012 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			

D206-642-XXX
SKIDTUBE (REF)


D2432-3
BEARPAW

SADDLE NOT SHOWN IN
THIS VIEW FOR CLARITY

**Figure 1a - Bearpaw Location
(Top View)**



**Figure 1b - Bearpaw Installation (Side View)
(Installed on D206-642-311/-312/-313/-314 Skid tubes)**



**Figure 1c - Bearpaw Installation (Side View)
(Installed on D206-642-411/-412/-413/-414 Skid tubes)**

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED
BY: *[Signature]*
D. SHEPHERD (DE # 02)

DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN	AP
DRAWN	AP
CHECKED	<i>[Signature]</i>
MFG. APPR.	N/A
APPROVED	<i>[Signature]</i>
DE APPR.	<i>[Signature]</i>
DATE	12.07.05

DART AEROSPACE LTD
HAWKESBURY, ONTARIO, CANADA

DRAWING NO. REV. A
DSI 9624 SHEET 2 OF 4
TITLE SCALE
BEARPAW INSTALLATION NTS

COPYRIGHT © 2012 BY DART AEROSPACE LTD
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS
NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT
WRITTEN PERMISSION FROM DART AEROSPACE LTD.





Figure 2 - D4011-1 Clamp Installation

4.0 PARTS LIST

QTY -115	PART NUMBER	DESCRIPTION
	D407-559-115	BEARPAW INSTALLATION
12	D2274	RADIUS BLOCK
12	D2529	WASHER
2	D2432-3	BEARPAW
6	D4011-1	CLAMP
6	D4012-1	CUSHION
12	AN4-20A	BOLT
12	AN960JD416	WASHER (NAS1149D0463J)
12	MS21042L4	NUT

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: 
D. SHEPHERD (DE # 02)

DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN	AP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AP		
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9624	SHEET 3 OF 4
APPROVED		TITLE	SCALE
DE APPR.		BEARPAW INSTALLATION	NTS
DATE	12.07.05	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

5.0 WEIGHT AND BALANCE

INSTALLATION	WEIGHT	LATERAL		LONGITUDINAL	
		ARM	MOMENT	ARM	MOMENT
D407-559-115 Bearpaw Installation (Bell 407 High Gear)	13.9 lb 6.30 kg	0.0 in 0.0 m	0.0 in-lb 0.0 m-kg	148 in 3.76 m	2057 in-lb 23.69 m-kg
D407-559-115 Bearpaw Installation (Bell 206L/407 Low Gear)	13.9 lb 6.30 kg	0.0 in 0.0 m	0.0 in-lb 0.0 m-kg	149 in 3.78 m	2071 in-lb 23.81 m-kg
D407-559-115 Bearpaw Installation (Bell 206 L High Gear)	13.9 lb 6.30 kg	0.0 in 0.0 m	0.0 in-lb 0.0 m-kg	157 in 3.99 m	2182 in-lb 25.14 m-kg

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY: 
D. SHEPHERD (DE # 02)

DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN	AP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AP		
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9624	SHEET 4 OF 4
APPROVED		TITLE	SCALE
DE APPR.		BEARPAW INSTALLATION	NTS
DATE	12.07.05	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

REFERENCE ONLY




Figure 2 - D4011-1 Clamp Installation

4.0 PARTS LIST

QTY -115	PART NUMBER	DESCRIPTION
	D407-559-115	BEARPAW INSTALLATION
12	D2274	RADIUS BLOCK
12	D2529	WASHER
2	D2432-3	BEARPAW
6	D4011-1	CLAMP
6	D4012-1	CUSHION
12	AN4-20A	BOLT
12	AN960JD416	WASHER (NAS1149D0463J)
12	MS21042L4	NUT

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY:
D. SHEPHERD (DE # 02)

DATE: 12.07.05
CERT. NO.: SH92-17
ISSUE NO.: 7

DESIGN	AP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AP		
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9624	SHEET 3 OF 4
APPROVED		TITLE	SCALE
DE APPR.		BEARPAW INSTALLATION	NTS
DATE	12.07.05	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

Work Order ID 147035

147035

Page 1

Friday, May 27, 2016 2:41:48 PM

Item ID: D407-559-115

Accept

N9000040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: 206L Series/407 Bearpaws - Run-on Landing Wearplate Comparibic

Start Date: 5/30/2016 Start Qty: 1.00 *1*

Cust Item ID:

Required Date: 6/7/2016 Req'd Qty: 1.00 *1*

Customer:

Reference:

Approvals: Process Plan: SPM Date: 6/05/27

Tooling: Date:

Run Start *NR1*

QC: Date: SPC (Y/N): Date:

Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

DSI 9624	REV A
----------	-------

100

Document Control

DAE

MAY 30 2016

100

DOCUMENT CONTROL

DC

Memo

0.00

Doc. Control -USB or Paperwork

Photocopy blue file and type labels per PPP D407-559-115 CHURCH

MUS MAY 30 2016

151

Pick Kit

0.00

151

Packaging

Memo

0.00

Packaging

MAY 30 2016

160

QC4- 100% Inspect kits for completeness

0.00

160

QC

Memo

0.00

Quality Control

Change Record

PAGE 1 OF 1

Part Number: D407-559-115_Description: BEARPAW INSTALLATION[illegible]